

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:				
OGM	Joe Helfrich Environmental Scientist III			
Company	Russell Hardy			

Inspection Report

Permit Number:	C0150007
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, November 23, 2004
Start Date/Time:	11/23/2004 10:00:00 AM
End Date/Time:	11/23/2004 2:00:00 PM
Last Inspection:	Wednesday, September 29, 2004

Inspector: Joe Helfrich, Environmental Scientist III

Weather: windy 40

InspectionID Report Number: 464

Accepted by: whedberg 12/6/2004

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO MID-CONTINENT REGION

Site: **HIDDEN VALLEY MINE**

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	960.00
Total Disturbed	6.70
Phase I	6.70
Phase II	
Phase III	

Federal	✓ Underground
☐ State	Surface
County	Loadout
✓ Fee	Processing
Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The purpose of this site visit was to conduct a partial inspection of the Hidden Valley facility specifically to evaluate the additional work to the silt fence. No off site impacts were noted. Russell Hardy accompanied the undersigned on this inspection.

Inspector's Signature

Date

Monday, November 29, 2004

Joe Helfrich, Environmental Scientist III Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov



Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Tuesday, November 23, 2004

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		\checkmark	
2.	Signs and Markers	V		V	
3.	Topsoil	✓		V	
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring		()		
4.e	Hydrologic Balance: Effluent Limitations	✓		~	
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	Roads: Construction, Maintenance, Surfacing				
16.Ł	Roads: Drainage Controls	~		V	
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Tuesday, November 23, 2004 Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The reclamation permit was renewed on January 29, 2002 and expires January 30, 2007. There are no amendments pending.

2. Signs and Markers

A sign containing the required information was posted at the entrance to the access road.

3. Topsoil

The topsoil on the road and pad area was moist and muddy as a result of the recent storms.

4.e Hydrologic Balance: Effluent Limitations

Water was flowing in Ivie Creek at approximately five cfs. Recent storms have resulted in increased flows in Ivie creek mostly during the month of October.

16.b Roads: Drainage Controls

The water bars along the access road had diverted runoff to the outslope of the road as designed.